



Synchrophasor Based Oscillation Detection in ERCOT Operations

Patrick Gravois
Grid Applications Support, ERCOT

**NASPI September 2017
Springfield, Massachusetts**

Agenda

- ERCOT Synchrophasor Network
- System Mode Analysis
- RTDMS Mode Meter Configuration
- Forced Oscillations Vs. System Modes
- North-South and Wind High Frequency Modes
- RTDMS Oscillation Detection Configuration
- Forced Oscillation Events
- Next Steps

The ERCOT Synchrophasor Project


- DOE funded project awarded to the Center for Commercialization of Emerging Technologies in January 2010
- Project Title: *Discovery Across Texas: Technology Solutions for Wind Integration in ERCOT*
- Synchrophasor component of project to demonstrate improved management of increasing amount of wind in ERCOT Interconnection
- Synchrophasor Project Participants: ERCOT, TOs, Electric Power Group – Lead for Synchrophasor portion of the project
- Installed EPG's Real Time Dynamic Monitoring System (RTDMS) and Phasor Grid Dynamic Analyzer (PGDA) in test environments for use by ERCOT Operations and Planning Engineers
- Project completed and reports submitted to DOE in December 2014

Details: <http://www.ercot.com/gridinfo/etts/ccet/index.html>


Number of PMUs Streaming Real Time Data to ERCOT

- **Total 109 PMUs @ 47 Locations**

- AEP: 64
- ONCOR: 17
- Sharyland: 5
- LCRA: 23




The Synchrophasor Data Communication Network



ERCOT System Modes Study

- As part of DOE project, EPG analyzed 3 years of PMU data to identify ERCOT system modes
- Used data from PMUs next to wind farms to identify oscillatory modes due to controllers
- Modes were analyzed to identify mode frequency, damping percentage, and energy level
- Mode meters in RTDMS were configured to track identified modes with the most common occurrence
- In addition, a mode meter was created to track the North-South system mode identified through PMU based event analysis

RTDMS System Mode Display



Issue with Tracking System Modes


- Mode meters not capable of identifying oscillations not specifically tracked
- Difficult to determine if meters were configured correctly and working
- Long periods time without any mode meter movement
- Were the oscillatory modes now heavily damped due to build out of CREZ transmission lines?
- Update to RTDMS version 17 and adjustment of time windows improved mode meter tracking
- Low damped modes don't usually show visible oscillations in PMU signal trends
- Studies will be needed to determine any possible control room procedures to address low damped modes. Is this even necessary?

System Modes Vs. Forced Oscillations?

- System modes are difficult to analyze and identify operational procedures for mitigation
- Forced oscillations seem to be more common and may be mitigated by finding the source signal and contacting responsible market participant
- Are the oscillatory modes found from the DOE/EPG study real system modes or reoccurring forced oscillations?
- Need for a tool to identify forced oscillations not tracked by system mode meters
- Have identified two common system modes, and will track all other oscillations with RTDMS' Oscillation Detection tool

ERCOT North to South System Modes

- Identified by PMU post event analysis using PGDA
- In most large unit trip events (>450 MW), units in the north and south are clearly shown to swing against each other
- Most common mode in the 0.6 – 0.7 Hz range, with a 0.9 Hz mode occasionally seen




ERCOT North to South System Modes

- Post-event Ring Down Analysis in PGDA usually calculates a damping of 8% or greater
- Only three occurrences in past three years in which damping was 5% or lower
- Since upgrade to RTDMS v17, North-South Modes have been well-tracked with usual damping in the 15-20% range
- Occasionally see damping drop to 5%
- Need to correlate pre-event damping to post-event damping
- Operator actions? Need for it?

Wind High Frequency Modes

- EPG identified high frequency modes (5.0 – 6.0Hz) in DOE project due to wind farm control systems
- Modes were typically low energy with one intermittent high frequency mode
- RTDMS v16 mode meter did not track modes very well due to a lack of higher energy event triggers
- RTDMS v17 mode meter has consistently shown damping of these modes in the 0-5% range with very low energy levels
- Intermittent oscillations have been seen consistently in the voltage and current measurements in west Texas beginning Fall 2016
- New solar farms are main suspect
- Forced oscillation related to system mode or independent?

West Texas Oscillations



West Texas Oscillations



West Texas Oscillations



West Texas Oscillations




West Texas Oscillations

- Began to see oscillations in October of 2016 and continued through Spring 2017
- Contacted TO and RE to see about identifying root cause
- TO was able to start sending PMU data for two other PMUs in the area in question
- Saw same oscillations with smaller amplitudes through the summer months
- Amplitudes have begun to pick back up in September
- Difficult to track root cause due to intermittency and different control systems with different owners likely interacting


RTDMS Oscillation Detection

- Identified a need to alert operation engineers to oscillations not being tracked by mode meters
- On July 6, oscillation with MVAR swing of 90 MVAR in Panhandle not detected by RTDMS Dashboard or Alarms
- Decided to upgrade to v17 for new oscillation detection application
- Used 7/6 event to configure new tool in Phasor Simulation for Operator Training (PSOT) and test environments
- Test environment actively picking up forced oscillations in multiple areas
- Once appropriate thresholds are determined to prevent over alarming, oscillation detection tool will be implemented on shift engineer desk
- Past and future oscillation events will be used to create shift engineer procedures

July 6 Oscillation Event in PSOT Dashboard





July 6 Event in PSOT Oscillation Detection Display



July 6 Event in PSOT Panhandle Display




Largest Voltage and Reactive Power Swings




Oscillation Detection Configuration in PSOT and Test Environments

- Wanted to develop necessary displays to alert operation and shift engineers to any sustained oscillations of certain magnitude
- Needed oscillation detection to pick up oscillations in all PMUs, not just a few
- Displays should also quickly lead operation engineers to the PMU and area with the largest voltage and power swings
- Need PSOT to replay event as though it is in real time to test configurations and alarms
- Event files also being created for oscillations that are not noticed in real time so they made be replayed
- For July 6 event, solution was to contact RE and have them turn off AVR


Sept. 13 Oscillation in Test Environment Replay




Sept. 13 Oscillation in Test Environment Replay




Sept. 13 Oscillation in Test Environment Replay



Sept. 13 Oscillation in Test Environment Replay



Sept. 13 Oscillation in Test Environment Replay



Oscillation Event Summary

- July 6 Oscillation – 0.45 Hz mode, ~3.5 kV pp, ~90 MVAR pp, ~65 Amp pp
 - Intermittent MVAR swings started on 6/28
 - Turned off AVR to mitigate oscillations
 - Event used in PSOT to configure Oscillation Detection in RTDMS
- August 18 – August 21 Oscillation – 0.66 Hz mode, ~40 MVAR pp
 - Occurred on 138 kV system, nearest PMU was on 345 kV so oscillation was damped down to ~4 MVAR at nearest PMU
 - Oscillation Detection in RTDMS was not configured at this time
 - RE was instructed to turn off AVR to mitigate oscillation
- September 11, 12, & 13 Oscillation – 0.60 Hz mode, ~1.1 kV pp, ~30 MVAR pp, ~75A pp
 - Occurred three consecutive days around noon for 1-2 hrs.
 - Contacted RE and they are looking into the issue but no solution yet
 - Oscillations from plant traced back to March with Data Mining
 - Oscillation detected in real time by RTDMS Oscillation Detection and event files created
- September 13-14 Oscillation – 0.1 Hz mode, ~14 MW pp, ~6 MVAR pp, ~25A pp
 - Oscillation started 11pm 9/13 lasted until 8:35am 9/14
 - No contact with RE but will observe

Next Steps

- Continue to tweak alarm and event thresholds for oscillation detection
- Bring oscillation detection to shift engineer desk
- Catalog oscillation events to begin development of shift engineer procedures for oscillations
- Upgrade PGDA with Automatic Event Mining tool to search for any missed oscillations or system modes
- Coordinate with appropriate market participants to find root cause and mitigate West Texas oscillations
- Determine if operation procedures are needed to mitigate low damped system modes and develop procedures if necessary



Questions?