

NERC

NORTH AMERICAN ELECTRIC
RELIABILITY CORPORATION

Phase Angle Monitoring:

*Industry Experience Following the 2011 Pacific
Southwest Outage Recommendation 27*

Ryan D. Quint, PhD, PE
NERC SMS Coordinator
NASPI Work Group Meeting
October 2016

RELIABILITY | ACCOUNTABILITY



- **Purpose:** Develop Technical Report on Phase Angle Monitoring and Alarming practices and experiences, and provide recommendations for future practices
 - In response to the 2011 Pacific Southwest Outage Recommendation #27
 - Was a NERC SAMS task but tabled until the NERC SMS kicked off
- **Topics:**
 - Phase Angle Fundamentals
 - Finding & Recommendation 27
 - Synchrocheck Relay Situational Awareness
 - EMS and PMU Application
 - Mitigation Strategies
 - Identifying Key Angle Differences & Correlating to System Conditions
 - Tying Phase Angles to Oscillations & System Studies
 - Phase Angle Monitoring Utility Practices in the West

- Finding #27

- *“Phase Angle Difference Following Loss of Transmission Line: “A TOP did not have tools in place to determine the phase angle difference between the two terminals of its 500 kV line after the line tripped. Yet, it informed the RC and another TOP that the line would be restored quickly, when, in fact, this could not have been accomplished.”*

- Recommendation #27

- *“TOPs should have: (1) the tools necessary to determine phase angle differences following the loss of lines; and (2) mitigation and operating plans for reclosing lines with large phase angle differences. TOPs should also train operators to effectively respond to phase angle differences. These plans should be developed based on the seasonal and next-day contingency analyses that address the angular differences across opened system elements.”*

- Line O/S = phase angle increases (generally); impedance increases
 - Large phase angles can lead to system instability and loss of synchronism for generating resources
- Synchrocheck relays monitor phase angle difference across breaker terminals
 - Reclosing line near generator with substantially large angle difference results in large transient torque on shaft of machine – related to rotor being out of phase with BPS. Can cause instant damage or cumulative fatigue of shaft
 - Often used on transmission system as well
- Synchrocheck relays measure voltage magnitude difference, frequency slip, and phase angle difference between voltage
 - Supervises against pre-determined, programmed setting prior to restoring line to service.

Network Abnormal Voltage Summary Bus -- Branch -- Angle Separation Threshold:

RTNET Last Solved: 06-Nov-2014 11:14:46 RTNET REALTIME OUTPUT PENDING

Branch Identifiers	Phase Angle Separation (Degrees)
ADLN MARK 1500: MARKPL TO ADLNT0	31.5
NAVA CRY5 1500: NAVAJO TO CRYSTAL	29.4
ELDO MOEN 1500: ELDORD TO MOENKOPI	29.3
POPU JBRI 1345: POPULUS TO JBRIDGER	29.1
POPU JBRI 2345: POPULUS TO JBRIDGER	29.1
ELDO LUGO 1500: LUGO TO ELDORD	28.0
CPJK OLDA 1500: CAPTJACK TO OLIND5	28.0
MCLL VICT 1500: MCLLGH TO VICTVL	25.8
JBRI THRE 1345: JBRIDGER TO THREEMLE	25.3
CORO SILV 1500: CORONADO TO SILVERKG	23.4
PERK MEAD 1500: PERKINS TO MEAD_Z	23.2
MEAD VICT 1287: MEAD_Z TO VICTVL	

Node Pair: **NP32** Description: **RECLOSE N.GILA - IMPERIAL VALLEY**

Station: **NGILA** **IVALLY** Active: Normal Limit:

Node: **950** **901** Eligible: Emergency Limit:

Angle: **-57.3** **-106.0** Disable: PBI Limit:

Calculated Angle Difference: **48.7** Key Equipment:

Network Basecase Violations Summary -- Angle -- Branch Interface Voltage MVAR Select Company:

Study STNET STUDY COMPLETE

Total Alarms: 0
Total Violations: 0

Alarm	New	Warn	Node Pair Identifier	Type	Actual Degree	- Violation Report - Rating	Deviation Degree	%	Rating Base	ETV Display
<input type="checkbox"/>	<input checked="" type="checkbox"/>		950 @NGILA - 901 @IVALLY	NP	48.7	49.0	-0.3	99.5	NORM	<input type="checkbox"/>

ANVIOL : <http://lepem2br/webfg/displays/stnet/N...>

Time Data

950 @NGILA - 901 @IVALLY

Time in: 08-Sep-2015 16:50

Time of Worst Violation: 08-Sep-2015 16:52

Value of Worst Violation: 52

Contingency Violations

Contingency Violations: Summary Branch Voltage -- Angle -- Interface

Component Violations: Summary Branch Voltage Angle Interface

Study Run STNET STUDY COMPLETE

Total Alarm: 0
 Total Violation: 64

Legend: w/RAS
 w/RAP
 Pre-RAP Only

Alarm	New	Warn	Node Pair Identifications	Type	Pre CTG Value	Post CTG Value	Rating	Dev	% Rating	Rating Base	ETV Display
			Contingency ID: SRP5L016	Description: *PALOVERDE-COLRIVER 500KV			Class: 500				
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	950 @NGILA - 901 @IVALLY	NP	48.74	65.57	50.00	15.57	131.1	EMER	<input type="checkbox"/>
							50.00	15.57	131.1	NORM	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	900B @DEVERS - 900F @PALVERDE	NP	-28.02	-54.80	50.00	4.80	109.6	NORM	<input type="checkbox"/>
			Contingency ID: SCE5L028	Description: *DEVERS_REDBLUF #2 500			Class: 500				
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	950 @NGILA - 901 @IVALLY	NP	48.74	55.05	50.00	5.05	110.1	EMER	<input type="checkbox"/>
							50.00	5.05	110.1	NORM	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	950 @NGILA - 901 @IVALLY	NP	48.74	54.59	50.00	4.59	109.2	EMER	<input type="checkbox"/>
							50.00	4.59	109.2	NORM	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	950 @NGILA - 901 @IVALLY	NP	48.74	52.85	50.00	2.85	105.7	EMER	<input type="checkbox"/>
							50.00	2.85	105.7	NORM	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	950 @NGILA - 901 @IVALLY	NP	48.74	51.78	50.00	1.78	103.6	EMER	<input type="checkbox"/>
							50.00	1.78	103.6	NORM	

CTG_VIOLATION_ANGLE : http://lepem2br/webfg/displ...
✖


Angle Violations

Monitored Element Violated
950 @NGILA - 901 @IVALLY

Time In: 08-Sep 17:01
 Time Worst: 08-Sep 17:01

Worst Violation
 Value : 65.57
 Rating: 50.00
 % Rating: 131.1
 Rate Level: EMER

Visualization of RTCA Results at APS





GRLX Geo Details


Asset Type: Substation
 Name: GRLX
 Description: GREENLEE SWTC
 Flags: 0x4000006


No.	Contingency (8)	Voltage	Equip. Type	Equipment	Status	Percent	Timer
1	APX-RTX 230KV	345KV	Xfmr	T321 A	SHRT	155	3
2	DDX-RTX 230KV	345KV	Xfmr	T321 A	SHRT	145	3
3	VAX 345H38KV X	345KV	Xfmr	T321 A	SHRT	103	3
4	PWZX-SOX 345KV	345KV	Xfmr	T321 A	SHRT	101	3
5	AFTX-NMX 345KV	345KV	Xfmr	T321 A	SHRT	101	0
6	DDX-HKX 230KV	345KV	Xfmr	T321 A	SHRT	101	3
7	GNX-WNX	345KV	Xfmr	T321 A	SHRT	100	0
8	CH-SG 500KV	345KV	Xfmr	T321 A	SHRT	100	0

RTCA "Emergency" Summary: 03/30/2015 12:42:00 PM (USMT)



- Generation redispatch
 - Reducing generation on the sending end of the angle difference path
 - Increasing generation on the receiving end of the path
- Use of phase-shifting transformers to reduce power flow (if available)
- Reconfiguration of system topology to reduce power flow (if possible)
- Curtailment of interruptible load, if necessary
- Firm load shedding, if necessary
- Point-to-point transmission service curtailment
- Reconfiguration of in-series capacitors/reactors for compensation of transmission circuits





1. Contingency risk of interest is outage of the a transmission circuit and the phase angle difference across the terminals of that out-of-service circuit – exceeding synchrocheck relay limits
 - Post-contingency angle difference should be monitored in real-time.
 - PCs/RCs should identify key circuits for which monitoring is required.
 - Recommended that awareness of synchrocheck relay limit exceedances should be provided to system operator for EHV \geq 345 kV.
2. Phase angle differences for potential contingency conditions should be monitored in real-time and compared against synchrocheck relay settings, if applicable, using RTCA tools.
 - Any N-1 or credible N-2 or N-1-1 exceedances of these limits should be provided to system operator for advanced notice of potential line restoration issues.

3. Wide-area angle difference monitoring provides additional layer of situational awareness for system operators.
 - Limits based on known risks such as transient stability, voltage stability, small signal stability, or overloads can effectively be developed based on operations studies or advanced online applications.
4. Line-based angle difference monitoring and comparison with known synchrocheck relay limits is not presently a universally adopted operating practice. NERC SMS and OC should explore wider adoption of these practices.
5. In the West, phase angle difference is correlated to oscillatory stability issues, particularly during high transfer conditions.
 - Tools such as Mode Meter, Oscillation Detection, and Phase Angle Difference (PAD) should continue to be pursued for increased situational awareness and defense in depth.



Questions and Answers